

### Packaging instruction AL-West

Packaging, crates and stickers are available from the order list on our website or Transportation Service.  
Please note: Samples not packed according to this instruction cannot be accepted.

#### Soil samples

- Deliver in clean soil jars placed in a clean soil crate.
- Deliver in clean buckets.
- Adapt packaging to the quantity of samples delivered (23 kg at most).



#### Dirty soil crate



#### Asbestos in a dirty bucket



#### Asbestos samples in buckets

- Deliver in clean AL-West buckets marked with an asbestos label.
- Adapt packaging to the quantity of samples delivered (23 kg at most).
- Two options for double wrapping:
  1. For AL-West buckets, seal the lid with sturdy tape. The handle must be able to move freely so that the buckets remain stackable.
  2. For other packaging, double wrap it in a dedicated asbestos bag (thickness 0.2 mm). Place the knot (Gooseneck style) on the side so that the buckets remain stackable.

Please note: barcodes must remain visible.



**Packaging instruction AL-West**

**Packaging, crates and stickers are available from the order list on our website or Transportation Service. Please note: Samples not packed according to this instruction cannot be accepted.**

**Water samples**

- Deliver in clean, securely sealed bottles. Preferably in special water crates (with or without a small cup for the smaller bottles).
- In the event that larger numbers of bottles are delivered in a ground crate, prevent the bottles from rolling back and forth to reduce the risk of shattering.



**Bottles in crate, risk of shattering**



**Bottles firmly placed in crate, do not protrude above edge**



**Smaller packaging for asbestos samples**

Smaller asbestos samples that are not delivered in a bucket should always be double wrapped, with the proper asbestos warning label on top. Special (double) bags are available for this purpose.



**Special, urgent or highly contaminated samples.**

In the event samples that require special attention (e.g. urgent, AP04, dioxin, asbestos or highly contaminated samples) are delivered, they must be marked with special labels.

